










LUCAS - 23731

ALT16001

| | | |
|---|---|---|
|  |  |  |
| <p>WRT6558 Alternator Rotor</p> | <p>WST8558 STATOR (Alt. for 8559)</p> | <p>RTF3923 RECTIFIER</p> |
|  |  |  |
| <p>BRG63022RS BEARING</p> | <p>BKT4052 BRACKET</p> | <p>NSK6202M NSK Bearing</p> |
|  |  |  |
| <p>VRG3692 REGULATOR</p> | <p>SLR3922 SLIP RING</p> | <p>ABR5406 ALT BRUSH SET</p> |



LUCAS - 23731

ALT16001

| | | |
|---|--|--|
|  |  |  |
| <p>BHD3924 BRUSH HOLDER</p> | <p>EC3925 ALT COVER</p> | <p>EC4050 ACR PULLEY</p> |
|  |  |  |
| <p>EC3927 BEARING KIT</p> | <p>EC3940 ACR ALT CONN SOCKETS</p> | <p>KIT0001 ALT.REPAIR KIT</p> |
|  | | |
| <p>EC3940 ACR ALT CONN SOCKETS</p> | | |