






# LUCAS - 24137A

<b>WRT6564</b> ALT ROTOR (rep. WRT 6563)	<b>WST8564</b> STATOR 75 AMP	<b>RTF4952</b> RECTIFIER
<b>BKT44855</b> A133 DE RH Bracket	<b>BRG63022RS</b> BEARING	<b>BRG62022RS</b> BEARING
<b>VRG3687</b> REGULATOR	<b>SLR4922</b> SLIP RING	<b>ABR5407</b> ALT BRUSH SET



# LUCAS - 24137A

 A tan-colored plastic brush holder component, shown from a perspective view. It has a cylindrical top section and a base with several mounting points and a central opening.	 A dark brown plastic cover component, shown from a top-down perspective. It is circular with a raised rim and several small protrusions and recesses on its top surface.	 A collection of various electrical components for an alternator repair kit, including brushes, slip rings, a diode pack, and a stator assembly, arranged on a white surface with a faint "WOOD AUTO" watermark.
<p>BHD4924 BRUSH HOLDER</p>	<p>EC3935B PLASTIC COVER</p>	<p>KIT0004 ALT.REPAIR KIT</p>