












LUCAS - 23717A/E

		
<p>WRT6557 ALT ROTOR</p>	<p>WST8556 STATOR (Alt. for 8555)</p>	<p>RTF3923 RECTIFIER</p>
		
<p>BRG62022RS BEARING</p>	<p>BKT4052 BRACKET</p>	<p>NSK6202M NSK Bearing</p>
		
<p>VRG3692 REGULATOR</p>	<p>SLR3922 SLIP RING</p>	<p>ABR5406 ALT BRUSH SET</p>



LUCAS - 23717A/E

		
<p>BHD3924 BRUSH HOLDER</p>	<p>EC3925 ALT COVER</p>	<p>EC4050 ACR PULLEY</p>
		
<p>EC3926 BEARING KIT</p>	<p>EC3940 ACR ALT CONN SOCKETS</p>	<p>KIT0001 ALT.REPAIR KIT</p>
		
<p>EC3940 ACR ALT CONN SOCKETS</p>		