





| | | |
|---|---|---|
|  |  |  |
| <p>WRT6562 ALT ROTOR</p> | <p>WST8561 STATOR (Alt. for WST 8562)</p> | <p>RTF3953 RECTIFIER</p> |
|  |  |  |
| <p>BRG63022RS BEARING</p> | <p>BKT4052 BRACKET</p> | <p>NSK6202M NSK Bearing</p> |
|  |  |  |
| <p>VRG3699 REGULATOR (Alt. for 3696)</p> | <p>SLR3922 SLIP RING</p> | <p>ABR5406 ALT BRUSH SET</p> |



LUCAS - 23902

| | | |
|--|---|---|
|  |  |  |
| <p>BHD3924 BRUSH HOLDER</p> | <p>EC3931A ALT COVER</p> | <p>EC4050 ACR PULLEY</p> |
|  | | |
| <p>EC3940 ACR ALT CONN SOCKETS</p> | | |