



LUCAS - 24085A

<p>WRT6566 ALT ROTOR (Alt. for WRT 6567)</p>	<p>WST8566 STATOR</p>	<p>RTF4950 RECTIFIER</p>
<p>BRG62022RS BEARING</p>	<p>BRG62022RS BEARING</p>	<p>VRG3687 REGULATOR</p>
<p>SLR4922 SLIP RING</p>	<p>ABR5407 ALT BRUSH SET</p>	<p>BHD4924 BRUSH HOLDER</p>



LUCAS - 24085A

 A black plastic cover for the Lucas 24085A alternator, shown from a top-down perspective.	 A bearing kit consisting of several metal rings and bearings, arranged on a white background with a faint Wood Auto logo.	 An alternator repair kit containing various electrical and mechanical components, including a green alternator housing, brushes, and a diode pack, arranged on a white background with a faint Wood Auto logo.
<p>EC3930 A115 PLASTIC COVER (EURO)</p>	<p>EC3926 BEARING KIT</p>	<p>KIT0002 ALT.REPAIR KIT</p>